

Message

---

**From:** Mullin, Michelle [Mullin.Michelle@epa.gov]  
**Sent:** 10/9/2019 7:02:19 PM  
**To:** Moore, Kendall [moore.kendall@epa.gov]; Ramanauskas, Peter [ramanauskas.peter@epa.gov]; Peachey, Robert [peachey.robert@epa.gov]  
**Subject:** FW: PCB wipe sample results for SVEC 2019  
**Attachments:** Sky Valley EC - 2019 Annual PCB Wipe Sampling Report.pdf

Hi-

Here is the email where they indicated shrinking epoxy.

## Ex. 5 Deliberative Process (DP)

### Ex. 5 Deliberative Process (DP)

Michelle Mullin | PCB Coordinator and Team Leader | pronouns: she, her  
U.S. Environmental Protection Agency | Region 10  
Land, Chemicals and Redevelopment Division  
1200 6<sup>th</sup> Avenue | Ste 155  
Seattle, WA 98101  
p: 206.553.1616 | [mullin.michelle@epa.gov](mailto:mullin.michelle@epa.gov)

**From:** Piplic, Devlin <piplicd@monroe.wednet.edu>  
**Sent:** Friday, August 23, 2019 1:34 PM  
**To:** Amanda Zych <azych@snohd.org>; Ramanauskas, Peter <ramanauskas.peter@epa.gov>; Moore, Kendall <moore.kendall@epa.gov>; Mullin, Michelle <Mullin.Michelle@epa.gov>; rosenkransk@monroe.wednet.edu; Kevin Plemel <kplemel@snohd.org>; sfrederick@snohd.org  
**Cc:** John Mannix <mannixj@monroe.wednet.edu>; Fredrika Smith <smithf@monroe.wednet.edu>; Scott I. Jamieson <sij@pattersonbuchanan.com>  
**Subject:** PCB wipe sample results for SVEC 2019

Good Afternoon,

The District completed PCB wipe sample testing at Sky Valley Education Center. PBS was contracted to complete the representative wipe sampling agreed to as part of our Corrective Action Plan for Sky Valley Education Center.

PBS completed the representative wipe sampling on August 8<sup>th</sup>. They collected the required 25 percent sampling. The report and results are included in this email.


The results indicate we are getting some leaching through the initial red layer, but noting that is above the EPA threshold. It was observed some of the overlaying brown epoxy layer shrunk exposing the edges of the red epoxy layer. The District will be reapply an additional layer of brown epoxy over any impacted red epoxy layer exposures.

Please let me know if you have any questions or guidance regarding the District next step.

--

### Devlin Piplic

Director of Facilities  
200 East Fremont  
Monroe, WA 98272  
Office: 360.804.2679



Any dissemination or use of this information by a person other than the intended recipient is unauthorized and may be illegal. If you have received this e-mail in error, please immediately notify us by return e-mail. All email to and from this domain is archived as a public record in compliance with federal and state requirements. As such they may be both discoverable in a legal action and available through a public records request.